

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 1-31-2008 Operator Western Mineral SAPI # 300398 2334			
Property Name Hurt Well No. 1 Location: Unit Section 1 Township 35 Range 3			
Well Status (Shut-In or Producing) Tubing 63 Intermediate N/A Casing 64 Bradenhead			
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH			
PRESSURES: TIME BRADENHEAD INTERMEDIATE CASING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED	
5 minutes ONA GH	Steady Flow		
10 minutes ONA 64	Surges		
15 minutes 6 N/A 64	Down to Nothing		
20 minutes 6 N/A 64	Nothing X	NIA	
25 minutes	GasRC	JD MAR 3 '08	
30 minutes ONA CON	Gas & Water	CONS. DIV.	
	Water	DIST. 3	
If bradenhead flowed water, check all of the descriptions that apply below:  CLEAR FRESH SALTY SULFUR BLACK			
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE			
REMARKS: Who I comed the Prodonbood			
up it had zero pressure			
The same			
By Bob Chencult Witness_			
Pumper			
(Position)			
E-mail address bobe com. com			