

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 2200	& Operator: Elm I	Ridge Expl	loration CO LLC Al	PI #30-043- <u>Q</u> Q	518
			Location: UnitS		
Well Status (Shut-In o	Producing Tub	oing <i>/ 6 2</i> , I	ntermediate Casi	ng/87 Bradenl	nead <u>// 3</u>
	PRESSURES:	CASING	-	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes		180	Steady Flow		
10 minutes 8		182	Surges		
15 minutes 5		184	Down to Nothing	5	
20 minutes		/		,	
.25 minutes			Gas		
30 minutes					1
			Water		
If bradenhead flowed wa	ter, check all of the de	escriptions t	hat apply below:		272820
44			SULFUR BLACK	-	RECEIVED P
CLEAR FRESH SALTY SULFUR BLACK 5 MINUTE SHUT-IN BRADENHEAD 12 INTERMEDIATE REMARKS: REMARKS:					
				(19)	SIPIEIZINO
Ву			Witness		
Pumper (Position)	Dung				
E-mail address					