



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 2/8/08 Operator: Elm Ridge Exploration CO LLC API #30-039- 24145

Property Name Shelia Hixon Well No. 1 Location: Unit K Section 26 Township 25 Range 36

Well Status (Shut-In or Producing) Tubing 98 Intermediate N/A Casing 98 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	BRADENHEAD	INTERMEDIATE	CASING	FLOWED	FLOWED
5 minutes	<u>0</u>		<u>98</u>	Steady Flow	
10 minutes	<u>/</u>		<u>/</u>	Surges	
15 minutes	<u>/</u>		<u>/</u>	Down to Nothing	
20 minutes	<u>/</u>		<u>/</u>	Nothing	
25 minutes	<u>/</u>		<u>/</u>	Gas	
30 minutes	<u>/</u>		<u>/</u>	Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD _____ INTERMEDIATE _____

REMARKS:



By Legal Counsel

Witness _____

Pumper
(Position)

E-mail address _____