



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 2-10-08 Operator: Elm Ridge Exploration CO LLC API #30-039- 24331

Property Name Schmitz Fed 34 Well No. 3 Location: Unit 3 Section 34 Township 24N Range 14W

Well Status (Shut-In or Producing) Tubing 48 Intermediate Casing 48 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>	<u>N.A.</u>	<u>48</u>	Steady Flow <u> </u>	
10 minutes	<u>0</u>		<u>48</u>	Surges <u> </u>	
15 minutes	<u>0</u>		<u>48</u>	Down to Nothing <u> </u>	
20 minutes				Nothing <u> </u> ✓	
25 minutes				Gas <u> </u>	
30 minutes				Gas & Water <u> </u>	
				Water <u> </u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE

REMARKS:

hole in tubing - not pumping



By Wendall T. J.

Witness

Contact Pumper
(Position)

E-mail address