

(Position)

NEW MEXICO ENERGY, MUNERALS & NATURAL RESOURCES DEPARTMENT

DIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NIL 87410
[505] 334-8178 FAX; (505) 334-8170
http://emrurd.etale.nm.us/oct/District IIV3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

LHURON_ Date of Test 1/1/08 Operator MID LONT API#30-0 392 7794 Well No. 4/0 Location: Unit Section 12 Township Range 74 Property Name_RINCOW Well Status(Shut-In or Producing) Tubing 77 Intermediate Casing 157 OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH PRESSURES: BRADENHEAD INTERMEDIATE TIME INTERMEDIATE CASING FLOWED FLOWED 5 minutes Steady Flow____ 10 minutes___ Surges_____ 15 minutes Down to Nothing 20 minutes_ Nothing 25 minutes_ Gas____ 30 minutes Gas & Water___ Water____ If bradenhead flowed water, check all of the descriptions that apply below: CLEAR_____ FRESH___ SALTY___ SULFUR___ BLACK BRADENHEAD_ 5 MINUTE SHUT-IN INTERMEDIATE_ REMARKS: OIL CONS. DIV. DIST Witness MAINT PLANNER