

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION.

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178

FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 2-15-08 Operator: Elm Ridge Exp	oloration CO LLC API #30-039-	2914
Property Name Axi Apach of Well No. 11	Location: Unit K Section S Towns	ship 3 N Range 5
Well Status (Shaw Froducing) Tubing 8	Intermediate Casing 130 Braden	head <u> </u>
OPEN BRADENHEAD AND INTERMEDIATE TO	O ATMOSPHERE INDIVIDUALLY FOR 1:	5 MINUTES EACH
PRESSURES: TIME BRADENHEAD INTERMEDIATE CASING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	Steady Flow	
10 minutes	Surges	
15 minutes	Down to Nothing	
20 minutes	Nothing X	
25 minutes	Gas	
30 minutes	Gas & Water	
	Water	
If bradenhead flowed water, check all of the descriptions		1234567
CLEAR FRESH SALTY	SULFUR BLACK	A 000
5 MINUTE SHUT-IN BRADENHEAD	SULFUR BLACK INTERMEDIATE SULFUR BLACK INTERMEDIATE	RECEIVED MAR 2008 OIL CONS. DIV. DIST. 3
REMARKS:	125	OIL COMS. DIA. DIOI. 0
		18/18/19202122
Ву	Witness	
Pumper (Position)	•	
E-mail address		