



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-8178 FAX: (505) 334-6170
<http://emrur.state.nm.us/ocd/District/III3district.htm>

BRADENHEAD TEST REPORT

(submit 2 copies to above address)


Date of Test 12/20/07 Operator CHURON MID CONT API #30-0 390625

Property Name RINCON Well No. 76 Location: Unit H Section 34 Township 27N Range 7W

Well Status(Shut-In or Producing) Tubing 22 Intermediate 24 Casing 24 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes			Steady Flow	
10 minutes			Surges	
15 minutes			Down to Nothing	
20 minutes			Nothing	
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

By M. Oyer Witness _____
MAINT PLANNER
(Position)