



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-8178 FAX: (505) 334-6170  
[http://emurrd.state.nm.us/ocd/District II/3district.htm](http://emurrd.state.nm.us/ocd/District%20II/3district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 12/18/07 Operator CHILVROW API #30-0 39821975  
Property Name RINCON Well No. 88A Location: Unit J Section 13 Township 27 Range 7W  
Well Status(Shut-In or Producing) 79 Tubing 79 Intermediate 81 Casing 81 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes			Steady Flow	
10 minutes			Surges	
15 minutes			Down to Nothing	
20 minutes			Nothing	
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD Ø INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Miloz  
MAINT PLANNER  
(Position)

Witness \_\_\_\_\_

