



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT


(submit 1 copy to above address)

Date of Test 3-24-08 Operator Burlington Res. API #30-0 45-33601
Property Name McClanahan Well No. 18m Location: Unit I Section 13 Township 28 Range 10
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 146 Intermediate 191 Casing 194 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min					<u>203</u>
10 min					<u>205</u>
15 min					<u>200</u>
20 min					<u>195</u>
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	☒	
Gas		
Gas & Water		
Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1.9

REMARKS:

Nothing on braden head when opened.
Intermediate blew down in 7.25 minutes - (blew 1/2 open
for just 4 1/2 min.)

By Dan Ferguson
Lab & ops
(Position)

Witness Monica Kuehling

E-mail address _____