



(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
 Land Office Santa Fe
 Lease No. 07111
 Unit Storey

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 17, 19 57

Well No. 7-C(18) is located 290 ft. from N line and 1750 ft. from E line of sec. 27

NE Sec. 27 28N 9E G.M.P.M.

($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Astec P.C. Ext. 3 Blanco San Juan New Mexico

(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6834 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 7-16-57, Total Depth 5200'.
 Ran 127 joints 7-5/8", 26.40#, J-55 casing (5189')
 set at 5199'. Two stage cementing tool at 3294'. First stage
 100 sacks regular cement, 100 sacks Pozmix with 4% gel and 1/8"
 Floccle per sack. Second stage 100 sacks regular cement,
 50 sacks Pozmix with 4% gel and 1/8" Floccle per sack.
 Held 1000' 30 minutes.
 Top of cement by temperature survey on second stage at 2160'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Co.Address Box 997Farmington, New MexicoBy Original Signed D. C. JohnsonTitle Petroleum Engineer