

(SUBMIT IN TRIPLICATE)
MAIN OFFICE
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 079082
Unit Northeast Blanco
Unit Agent No. 1, Sec. 929

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

DAKOTA - MESAVERDE DUAL

June 17, 1960

Well No. 12-18 is located 2500 ft. from N line and 2500 ft. from E line of sec. 18

NE/4 Section 18
(1/4 Sec. and Sec. No.)

30N
(Twp.)

7W
(Range)

RMPM
(Meridian)

Blanco Mesaverde - S. Los Pinos
(Field)

San Juan
(County or Subdivision)




The elevation of the derrick floor above sea level is 6295 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 6/10/60, a cast iron bridge plug was set at 6510' with one sack cement. Dakota Zone plugged and abandoned.



RECEIVED

JUN 20 1960

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Blackwood & Nichols Company

Address P.O. Box 1237

Durango, Colorado

Original Signed
By Delasso Loos

Title Field Superintendent