



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 3/29/08 Operator: Elm Ridge Exploration CO LLC API #30-039- 05355

Property Name Wernitzide #4 Well No. 1 Location: Unit N Section 21 Township 24 Range 1

Well Status (Shut-In or Producing) Tubing 35 Intermediate 0 Casing 42 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>	<u>0</u>	<u>42</u>	<u>N/A</u>	
10 minutes	<u>0</u>		<u>42</u>		
15 minutes	<u>0</u>		<u>42</u>		<u>RCUD APR 7 '08</u> <u>OIL CONS. DIV.</u> <u>DIST. 3</u>
20 minutes					
25 minutes					
30 minutes					
				Steady Flow	
				Surges	
				Down to Nothing	
				Nothing	
				Gas	
				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

Plumbed up Bradenhead & Tested.
Had to weld collar on surface pipe.

By

Dudley Wilder

Witness

Pumper
(Position)

E-mail address _____

04/08/2008 Our record show
operator as Lawrence W Ritter
HW