

1439

30-045-25699

E

DATA SHEET FOR DEEP GROUND BED CATHODIC PROTECTION WELLS
NORTHWESTERN NEW MEXICO

(Submit 3 copies to OCD Aztec Office)

Operator MERIDIAN OIL INC. Location: Unit F Sec. 11 Twp 28 Rng 7Name of Well/Wells or Pipeline Serviced ANGEL PEAK #27

cps 6020W

Elevation N/A Completion Date 10/21/83 Total Depth 220. Land Type* N/ACasing, Sizes, Types & Depths N/AIf Casing is cemented, show amounts & types used N/A

If Cement or Bentonite Plugs have been placed, show depths & amounts used

N/A

Depths & thickness of water zones with description of water when possible:

Fresh, Clear, Salty, Sulphur, Etc. 70'Depths gas encountered: N/AType & amount of coke breeze used: N/ADepths anodes placed: N/ADepths vent pipes placed: N/AVent pipe perforations: N/ARemarks: gb #1

RECEIVED
MAY 31 1991
OIL CON. DIV.
DIST. 3

If any of the above data is unavailable, please indicate so. Copies of all logs, including Drillers Log, Water Analyses & Well Bore Schematics should be submitted when available. Unplugged abandoned wells are to be included.

*Land Type may be shown: F-Federal; I-Indian; S-State; P-Fee.
If Federal or Indian, add Lease Number.

CORROSION CONTROL CO. • 300 West Chaco • Aztec, New Mexico

LOCATION

Union of Texas

DAILY DRILLING REPORT

10/21, 1983

FARM:

Angel Peak 27

WELL NUMBER:

08

SECTION:

F 11

TOWNSHIP:

28

RANGE:

07

water at 70 feet

HOLE MADE:

220

DESCRIPTION OF FORMATION

FROM	TO	FORMATION IS	COLOR
0	70	Sand and Water	
70	90	Bentonite	
90	140	Shale	
140	160	Bentonite	

REMARKS:

Driller

Tool Dresser

HOLE MADE:

DESCRIPTION OF FORMATION

FROM	TO	FORMATION IS	COLOR
160	220	Sandy Shale	

REMARKS:

Driller

Tool Dresser

HOLE MADE:

DESCRIPTION OF FORMATION

FROM	TO	FORMATION IS	COLOR

REMARKS:

Driller

Lerence Largent

Tool Dresser