



& NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-8170
<http://enrwd.state.nm.us/ocd/District%203/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test March 27-08 Operator Chevron Midcont API #30-0 39-66891


Property Name Rincon Unit Well No. 34 Location: Unit K Section 28 Township 21N Range 7W

Well Status (Shut-In or Producing) Initial PSI: Tubing 143.3 Intermediate - Casing 143.4 Bradenhead 0.0 Psi

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0.0</u>		<u>143.4</u>		
10 min	<u>0.0</u>		<u>143.4</u>		
15 min	<u>0.0</u>		<u>143.4</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	☒	
Gas		
Gas & Water		
Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.0 Psi INTERMEDIATE -

REMARKS:

Found 0.0 Psi on Bradenhead. No Flow.

2008 March 27

Witness -

(Position)

Oil address -