



& NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-8178 FAX: (505) 334-6170
<http://emrmd.state.nm.us/bcd/District%203/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test March 13, 2008 Operator Phannon Mid Cont. L.P. API #30-0 39-07008

Property Name Phannon Well No. 185 Location: Unit A Section 22 Township 07 Range 7

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 150.5 Intermediate — Casing 149.3 Bradenhead 0.0 Psi

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM		
	BH	Bradenhead Int	Csg	Int	Csg	
5 min	0.0		149.3			
10 min	0.0		149.3			
15 min	0.0		149.4			
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	✓	
Gas		
Gas & Water		
Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.0 Psi INTERMEDIATE —

REMARKS:

Found 0.0 Psi No Flow.
New Valve on Bradenhead.

By William Hattell

(Position)

Witness

3/13/08

Shelly Seaton
Value Open - Unable to Close /
Full of Water. Needs repair

Oil address —