



& NATURAL RESOURCES DEPARTMENT

1000 RIO BRAZOS ROAD
AZTEC NM 87413
(505) 334-8178 FAX: (505) 334-8170
<http://enrwd.state.nm.us/ocd/District%203/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

039-07018

Date of Test March 25-08 Operator Chevron Midcont API #30: _____

Property Name Rincon Unit Well No. 118 Location: Unit A Section 22 Township 22N Range 6W

Well Status (Shut-In or Producing) Initial PSI: Tubing 40.3 Intermediate - Casing 72.4 Bradenhead 0.0 Psig

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing TIME	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0.0	-	72.4		
10 min	0.0		72.3		
15 min	0.0		72.4		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow _____
Surges _____
Down to Nothing _____
Nothing ☒ _____
Gas _____
Gas & Water _____
Water _____

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.0 Psig INTERMEDIATE _____

REMARKS:

Found 0.0 Psig No Flow.

W. L. Hottel

Witness _____

(Position)

Oil address _____

