



& NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emvrd.state.nm.us/ocd/District/03/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

39-07026

Date of Test March 17-08 Operator Chevron MidCont API #30-0

Property Name Tencon Unit Well No. 157 Location: Unit N Section 18 Township 7N Range 6W

Well Status (Shut-In or Producing) Initial PSI: Tubing 75.3 Intermediate - Casing 73.1 Bradenhead 0.0 Psi


OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0.0		73.1		
10 min	0.0		73.7		
15 min	0.0		74.4		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing ☒	
Gas	
Gas & Water	
Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.0 Psi INTERMEDIATE _____

REMARKS:

Found just a Puff. No Flow. New Valve on Bradenhead.

by Lillard Hattell

Witness _____

(Position)

il address _____