



& NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emurd.state.nm.us/ocd/District/EI3d5a1r1c.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test March 18-08 Operator Chevron MidCont API #30-0 396 7045

Property Name Pinecon Unit Well No. 81 Location: Unit K Section 17 Township 24N Range 6W ✓

Well Status (Shut-In or Producing) Initial PSI: Tubing 75.7 Intermediate — Casing 99.1 Bradenhead 0.5 Psi

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0.0</u>		<u>99.1</u>		
10 min	<u>0.0</u>		<u>99.1</u>		
15 min	<u>0.0</u>		<u>99.0</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.5 Psi INTERMEDIATE _____

REMARKS:

Blew Down in a Puff No Flow.

y 2nd Street Hotel.

Witness _____

(Position)

il address _____

