



& NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://enrwd.state.nm.us/ocd/District/E/3/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test March 13-08 Operator Chevron Mid Con API #30-0 39-07061

Property Name Rincon Unit Well No. 87 Location: Unit F Section 13 Township 27N Range 2W

Well Status (Shut-In or Producing) Initial PSI: Tubing 32.5 Intermediate - Casing 34.2 Bradenhead 0.0 Psi

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>34.2</u>		
10 min	<u>0.0</u>		<u>34.2</u>		
15 min	<u>0.0</u>		<u>34.2</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	☒
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.0 Psi INTERMEDIATE

REMARKS:

Found 0.0 Psi on Bradenhead.

by DeLilled Mattell

Witness

(Position)

il address

