



OIL & NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emrmd.state.nm.us/ocd/District/District3.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test March 17-08 Operator Chevron MidCont API #30-0 3907071

Property Name Bencon Unit Well No. 159 Location: Unit G Section 18 Township 11N Range 6W

Well Status (Shut-In or Producing) Initial PSI: Tubing 52 Intermediate - Casing 69 Bradenhead 0.8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	Bradenhead	INTERM				
	BH	Int	Csg	Int	Csg	
TIME						
5 min	<u>0.0</u>		<u>69.0</u>			
10 min	<u>0.0</u>		<u>69.0</u>			
15 min	<u>0.0</u>		<u>68.9</u>			
20 min						
25 min						
30 min						

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	☒	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.0 Psi INTERMEDIATE

REMARKS: Found 0.8 Psi Blew Down in 2 Sec. No Flow.

by William Hattell

Witness

(Position)

il address

