



& NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://enr.nrd.state.nm.us/ocd/District%203/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test March 13, 2008 Operator Chermon Mid Cont LP API #30-0 39-07072

Property Name Reisen Unit Well No. 85 Location: Unit H Section 5 Township 7 Range 7

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 118.7 Intermediate 128.6 Casing 127.8 Bradenhead 0.5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0.0</u>		<u>127.8</u>	<u>128.6</u>	
10 min	<u>0.0</u>		<u>127.9</u>	<u>127.7</u>	
15 min	<u>0.0</u>		<u>127.8</u>	<u>127.7</u>	
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

Steady Flow 128.6

Surges

Down to Nothing ☒

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.0 INTERMEDIATE 127.7

REMARKS:

Found 0.5 psi Blew down to 0.0 2 sec 1" Valve.
Installed a new Valve on Bradenhead.

By William Blatter

(Position)

Witness

3/13/08

Sherry Carson NMCCO

Unable to test because Btl
Value Open / Unable to Close
Valve. Needs repair!

