



OIL & NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emvrd.state.nm.us/ocd/District/III/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test March 25-08 Operator Chevron MidCont API #30-0 79-20495

Property Name Pincon Unit Well No. 190 Location: Unit Section 17 Township 27N Range 4W


Well Status (Shut-In or Producing) Initial PSI: Tubing 59.6 Intermediate Casing 0.0 Bradenhead 0.0 Psig

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0.0</u>		<u>0.0</u>		
10 min	<u>0.0</u>		<u>0.0</u>		
15 min	<u>0.0</u>		<u>0.0</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing ☒	
Gas	
Gas & Water	
Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.0 Psig INTERMEDIATE

REMARKS: This Well is a slim Hole found 0.0 Psig on Casing.

By William Hottel

Witness

(Position)

Oil address