



& NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emwd.state.nm.us/ocd/District%203/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test March 13, 2008 Operator Churron M. Gutierrez API #30-0 39-20 738

Property Name Pinon Unit Well No. 199 Location: Unit 0 Section 14 Township 27 Range 7

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 34.6 Intermediate 87.5 Casing Bradenhead W

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0.0		87.5		
10 min	0.0		87.5		
15 min	0.0		87.5		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas <u>Whisper</u>	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS:

Whisper for 3 sec. Down to 0.0 psi. Replaced Casing Valve.

By Richard Hottel

(Position)

Witness Shelly Goben NMCD

3/13/08 Unable to test Valve open
& no BH plumb to surface
(Stim hole?) SC

* 24 hour Retest *

