



& NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emrard.state.nm.us/ocd/District%203/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test March 17-08 Operator Chavron Mid Cont API #30-0 39-2 1707

Property Name Bencon Unit Well No. 79A Location: Unit D Section 17 Township 27N Range 6W

Well Status (Shut-In or Producing) Initial PSI: Tubing 53.4 Intermediate Casing 103.7 Bradenhead 2.1 Psi

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead			INTERM			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
TIME								
5 min	0.0		103.7				Steady Flow	
10 min	0.0		103.1				Surges	
15 min	0.0		102.8				Down to Nothing	✓
20 min							Nothing	
25 min							Gas	
30 min							Gas & Water	
							Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.0 Psi INTERMEDIATE

REMARKS:

Found 2.1 Psi Blew Down in 3 sec 2" Valve.



by William Hottell

Witness

(Position)

il address 759-8203