



& NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrmd.state.nm.us/ocd/District 3/district.htm](http://emrmd.state.nm.us/ocd/District%203/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test March 13-08 Operator Chevron MidCont API #30-0 79# 21975

Property Name Rincon Unit Well No. 88A Location: Unit 2 Section 13 Township 27 Range 7W

Well Status (Shut-In or Producing) Initial PSI: Tubing 0.0 Intermediate — Casing 144.9 Bradenhead 0.0 Psig

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>144.9</u>		
10 min	<u>0</u>		<u>144.9</u>		
15 min	<u>0</u>		<u>144.9</u>		
20 min	<u>0</u>		<u>144.9</u>		
25 min	<u>0</u>		<u>144.9</u>		
30 min	<u>0</u>		<u>144.9</u>		

FLOW CHARACTERISTICS

Steady Flow _____
Surges _____
Down to Nothing _____
Nothing _____
Gas Whisper
Gas & Water _____
Water _____

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.0 Psig INTERMEDIATE _____

REMARKS:

Found 0.0 Psig Flowing a whisper of Gas. No Pressure Buildup.

by DeLillard Hattell

Witness _____

(Position)

il address _____

