



& NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://enrwd.state.nm.us/ocd/District/EI/3/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test March 08 Operator Chevron Midcont API #30-0 3924711

Property Name Rincon Unit Well No. 271 Location: Unit 01 Township 26N Range 7W

Well Status (Shut-In or Producing) Initial PSI: Tubing 229 Intermediate — Casing 44.0 Bradenhead 0.0 Psi

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

Testing Bradenhead INTERM
BH Int Csg Int Csg

BRADENHEAD INTERMEDIATE

TIME	BH	Int	Csg	Int	Csg
5 min	0.0		44.0		
10 min	0.0		44.0		
15 min	0.0		44.0		
20 min					
25 min					
30 min					

Steady Flow

Surges


Down to Nothing

Nothing ☒

Gas

Gas & Water

Water



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.0 Psi INTERMEDIATE —

REMARKS:

Found 0.0 Psi No Flow.

by S. Leland Hottell

Witness —

(Position)

Oil address —