



& NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6170 FAX: (505) 334-6170
<http://enrwd.state.nm.us/bcd/District/E/3/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test March 13-08 Operator Chevron Mid Cont API #30-0 3425062

Property Name Pincon Unit Well No. 167 DK Location: Unit DK Section: 13 Township 27N Range 7W

Well Status (Shut-In or Producing) Initial PSI: Tubing 46.1 Intermediate — Casing 73.5 Bradenhead 0.0 Psi

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0.0		73.5		
10 min	0.0		73.5		
15 min	0.0		73.5		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing ☒	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.0 Psi INTERMEDIATE —

REMARKS:

Found 0.0 Psi on Bradenhead.

by J. S. Lillard Hattel

Witness —

(Position)

il address —

