



OIL & NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/M3/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test March 26-08 Operator Chevron Mid Cont API #30-0 3925223

Property Name Pincon Unit Well No. 182 E Location: Unit E Section 26 Township 22N Range 4W


Well Status (Shut-In or Producing) Initial PSI: Tubing 96.3 Intermediate - Casing 186.6 Bradenhead 0.1 Psi

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0.0</u>		<u>186.6</u>		
10 min	<u>0.0</u>		<u>186.6</u>		
15 min	<u>0.0</u>		<u>186.6</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	☒
Nothing	
Gas	
Gas & Water	
Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.0 Psi INTERMEDIATE -

REMARKS: Found 0.1 Psi on Bradenhead Blew Down in a Puff.
No Flow.

By ?

Witness -

(Position)

il address -