



& NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6176 FAX: (505) 334-6170
[http://emrmd.state.nm.us/ocd/District III/district.htm](http://emrmd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test March 13-08 Operator Chevron Mid Cont API #30-0 3925491

Property Name Rincon Unit Well No. 177-E Location: Unit E Section 13 Township 22 Range 7W
LOT 2


Well Status (Shut-In or Producing) Initial PSI: Tubing 41.4 Intermediate — Casing 37.9 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0.0		37.9		
10 min	0.0		37.9		
15 min	0.0		37.9		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	☒
Gas	
Gas & Water	
Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.0 Psig INTERMEDIATE —

REMARKS:

Found 0.0 Psig on Bradenhead.

by William Hattell

Witness —

(Position)

Found Bradenhead Valve OPEN. Test in 24 Hrs

il address —