



& NATURAL RESOURCES DEPARTMENT

ACTING DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-8170
<http://emrwd.state.nm.us/ocd/District/EU3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test March 18-08 Operator Chevron MidCont API #30-0 039-26490
Property Name Benson Unit Well No. 157 M Location: Unit 5 Section 18 Township 27N Range 6W
Well Status (Shut-In or Producing) Initial PSI: Tubing 67.7 Intermediate — Casing 72.3 Bradenhead 0.1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				FLOW CHARACTERISTICS	
	BH	Bradenhead Int	Csg	INTERM Int	Bradenhead	INTERMEDIATE
5 min	0.0		72.6			
10 min	0.0		72.5			
15 min	0.0		72.6			
20 min						
25 min						
30 min						

Steady Flow

Surges


Down to Nothing ☒

Nothing

Gas

Gas & Water

Water



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.0 Psig INTERMEDIATE —

REMARKS: Found 0.1 Psig Blew Down a Whisper. No Flow.

by William Hattell

Witness —

(Position)

mail address 759-8703