



& NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emrwd.state.nm.us/ocd/District/III3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test March 18-08 Operator Chercon MidCont API #30-0 3927293
Property Name Fincon Unit Well No. 1614 Location: Unit F Section 17 Township 22N Range 16W
Well Status (Shut-In or Producing) Initial PSI: Tubing 90.6 Intermediate --- Casing 202.2 Bradenhead 0.0 Psi

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0.0</u>		<u>202.2</u>		
10 min	<u>0.0</u>		<u>202.6</u>		
15 min	<u>0.0</u>		<u>202.6</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing ☒	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR --- FRESH --- SALTY --- SULFUR --- BLACK ---

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.0 Psi INTERMEDIATE ---

REMARKS:

Found 0.0 Psi. No flow.

v. DeLland Hattell

Witness ---

(Position)

Oil address ---

