



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 12 May 2008 Operator Lively Exp API #30-0 45-21107  
Property Name Lively Well No. 6 Location: Unit 4 Section 30 Township 29N Range 8W  
Well Status (Shut-In or Producing) Tubing 144 Intermediate 0 Casing 157 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>	<u>0</u>	<u>157</u>	Steady Flow	
10 minutes	<u>0</u>	<u>0</u>	<u>156</u>	Surges	
15 minutes	<u>0</u>	<u>0</u>	<u>156</u>	Down to Nothing	
20 minutes				Nothing	<u>X</u>
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

By Russell Benson

Witness \_\_\_\_\_

(Position)

E-mail address \_\_\_\_\_

