



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
www.emnrd.state.nm.us/ocd/District 3/district3.htm

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 9 May 2008 Operator Lively Exp. API #30-0 45-21074  
Property Name Lively Well No. 3 Location: Unit N Section 9 Township 29N Range 8W  
Well Status (Shut-In or Producing) Tubing 141 Intermediate 0 Casing 286 Bradenhead 31

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	BRADENHEAD	INTERMEDIATE	CASING	FLOWED	FLOWED
5 minutes	<u>0 TLTM</u>	<u>0</u>	<u>288</u>	Steady Flow	
10 minutes	<u>0</u>	<u>0</u>	<u>288</u>	Surges	
15 minutes	<u>0</u>	<u>0</u>	<u>289</u>	Down to Nothing	<u>X</u>
20 minutes				Nothing	<u>X</u>
25 minutes				Gas	<u>X</u>
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD TLTM INTERMEDIATE 0

REMARKS:

By Russell Barrow Witness \_\_\_\_\_

Piemonte  
(Position)

E-mail address \_\_\_\_\_

