



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test: 5-21-08 Operator: Merrion Oil & Gas API #: 30-039-27563

Property Name: Blueberry Buckle Com Well No.: 2 Location: Unit: A Section: 32 Township: 30N Range: 7W

Well Status (Shut-In or Producing) Tubing 30 Intermediate Casing 65 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>		<u>65</u>	Steady Flow	
10 minutes	<u>0</u>		<u>65</u>	Surges	
15 minutes	<u>0</u>		<u>65</u>	Down to Nothing <input checked="" type="checkbox"/>	
20 minutes				Nothing	
25 minutes				Gas <input checked="" type="checkbox"/>	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

RCVD JUN 10 '08
OIL CONS. DIV.
DIST. 3

REMARKS:

By Frank Hancock

Witness

(Position)

pumper

E-mail address