RECEIVED

In Lieu of Form 3160 (June 1990)

UNITED STATES DEPARTMENT OF INTERIOR BUREAU OF LAND MANAGEMENT

MAY 28 2008

FORM APPROVED Budget Bureau No 1004-0135

	Burganasi	
	Tareau of Land Manage	
	Familiagemen	ŧ
INDDV NOTICE AND DEDODTS ON WEI	Bureau of Land Managemen	_

Expires March 31, 1993

SUNDRY NOTICE AND REPORTS ON WELLS Farmington Field Office Do not use this form for proposals to drill or to deepen or reentry to a different reservoir Use "APPLICATION TO DRILL" for permit for such proposals		3."	Lease Designation and Serial No NMSF-078772
		6.	If Indian, Allottee or Tribe Name RCUD MAY 30 '08
	SUBMIT IN TRIPLICATE	7.	If Unit or CA, Agreement Designation Rosa Unit OIL CONS. DIV.
1.	Type of Well Oil Well Gas Well X Other	8.	Well Name and No DIST. 3 Rosa Unit #151B
2.	Name of Operator WILLIAMS PRODUCTION COMPANY	9.	API Well No 30-045-34252
3.	Address and Telephone No PO Box 640 Aztec, NM 87410-0640	10.	Field and Pool, or Exploratory Area BLANCO MV
4	Location of Well (Footage, Sec, T, R., M, or Survey Description) 1275' FNL & 565' FWL Sec 33, T32N, R6W NMPM	11,	County or Parish, State San Juan, New Mexico

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA


TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent	Abandonment	Change of Plans	
	Recompletion	New Construction	
X Subsequent Report	Plugging Back	Non-Routine Fracturing	
	Casing Repair	Water Shut-Off	
Final Abandonment	Altering Casing	Conversion to Injection	
	X Other Surface Casing	Dispose Water	
		(Note. Report results of multiple completion	
		on Well Completion or Recompletion Report	
	· ·	and Log form.)	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is 13. directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work)*

5-26-08 - TD 12-1/4" SURFACE HOLE @ 345' AT 0500 HRS RUN 7 JTS 9-5/8", 36#, k-55, ST&C CASING SET @ 344'

CEMENT 9-5/8" CASING @ 343.94' - SHOE DEPTH / SINGLE SLURRY CEMENT JOB / 10 BBLS. FRESH WATER SPACER / 300 SXS TYPE 3 CEMENT + 2% CaCl-2 + .25#/SX CELLO FLAKE + 20.47 BBL, WATER = 48.83 BBL. (417 CuFt) SLURRY @ 14.5 PPG (YIELD = 1.39 / WGPS = 6.84) / DISPLACE WITH 23 BBL. WATER / PLUG DOWN ON 5/26/2008 @ 12:15 PM 30 BBL .OF CEMENT RETURNS TO SURFACE .

5-27-08 - INSTALL TEST PLUG & TEST BOP PIPE & BLIND RAMS, CHOKE MANIFOLD VALVES, MUD CROSS VALVES, FLOOR VALVE KELLY @ 250# 5-MIN EACH & 1500# 10-MIN EACH. TEST 9 5/8" CSG @ 1500# 30-MIN. TEST PUMP & TEST CHARTS USED ON ALL TEST. ALL TESTED GOOD. ✔



14.	I hereby certify that the foregoing is true and correct Signed Larry Higgins	Title <u>Drilling C O.M</u>	Date <u>5-28-08</u>	
	(This space for Federal or State office use)			
•	Approved by	Title		Date
	Conditions of approval, if any			,

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction



