



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT


(submit 1 copy to above address)

Date of Test 7-23-08 Operator Burlington API #30-0 4522778
Property Name El Paso Well No. 1A Location: Unit Section 20 Township 29 Range 9
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 140 Intermediate 1A Casing 148 Bradenhead 102

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	Bradenhead		Csg	Int	
	BH	Int		Int	Csg
5 min			148		
10 min			149		
15 min			149		
20 min					
25 min					
30 min					

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	/	
Nothing		
Gas	/	
Gas & Water		
Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 1 INTERMEDIATE 1A

REMARKS:

Blew down in 3 seconds

By Russell Elliott
Lease Oper.
(Position)

Witness Monica Kuehling

E-mail address