NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3district.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-5-08 Operator Burlington Res. API #30-0 45-30289

Property Name Cain Well No. 1B Location: Unit M Section 30 Township 31 Range 10

Well Status(Shut-In or Producing) Initial PSI: Tubing 87 Intermediate 15 Casing 115 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min					115
10 min					115
15 min					115
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		✓
Nothing	✓	
Gas		✓
Gas & Water		
Water		

RCVD SEP 5 '08
OIL CONS. DIV.
DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ____ FRESH ____ SALTY ____ SULFUR ____ BLACK ____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: Braden head had puff when opened. Intermediate blew med hard for 2 minutes then down to nothing in 2 min 15 sec.

By Brandon Ferrari Witness Monica Kuehling

(Position)

E-mail address