In Lieu of Form 3160

UNITED STATES DEPARTMENT OF INTERIOR

RECEIVE AUG 1 9 2008

FORM APPROVED
Budget Bureau No. 1004-0135

(June 1990	BUREAU OF L.	AND MANAGEMENT	AUU 1 3 2000		pires: March 31, 1993	
SUNDRY NOTICE AND Do not use this form for proposals to drill or to deepen or TO DRILL" for permi		REPORTS ON WELLS r reentry to a different reservoi	read of Land manager Farmington Field Offic ir. Use "APPLICATION		esignation and Serial No.	
		it for such proposals		6. If Indian	If Indian, Allottee or Tribe Name	
	SUBMIT IN T	RIPLICATE		7. If Unit o	or CA, Agreement Designation	
1.	Type of Well Oil Well Gas Well X Other				Well Name and No. Rosa Unit #264A	
2.	Name of Operator WILLIAMS PRODUCTION COMPANY			API Well No. 30-039-30338		
3.	Address and Telephone No. PO Box 640 Aztec, NM 87410-0640). Field and Pool, or Exploratory Area BASIN FRUITLAND COAL	
4.	Location of Well (Footage, Sec., T., R., M., or AT SURF- 2165' FSL & 100' FWL SEC 23 BHL- 1000' FSL & 400' FEL SEC 22			I	or Parish, State riba, New Mexico	
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
	TYPE OF SUBMISSION TYP			OF ACTION		
te-	Notice of Intent X Subsequent Report Final Abandonment	Recompletion Plugging Bac Casing Repa	Abandonment Change of Plans Recompletion New Construction Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Altering Casing Conversion to Injection		nstruction utine Fracturing hut-Off	
	i mai Abandonnien	X Other – <u>SUR</u>	=	(Note: Re	Dispose Water eport results of multiple completion Completion or Recompletion Report	
13.	Describe Proposed or Completed Operations (Odirectionally drilled, give subsurface locations					
8/17/08 TD- 12 '/'" SURFACE HOLE @ <u>347'</u> , 1630 HRS				RCVD AUG 27'08 OIL CONS. DIV.		
8/18/08 RAN 7 JTS, 9.5/8", 36#, K-55, 8rD - ST&C, CSG SET @ 336'. FC @ 287' CEMENT 9-5/8" CASING @ 336' - SHOE DEPTH / SINGLE SLURRY CEMENT JOB / 20 BBLS. FRESH WATER SPACER / 150 SXS TYPE 3 CEMENT + 2% CaCl-2 + .25#/SX CELLO FLAKE + 24.26 BBL. WATER = 81 BBL. (212 CuFt) SLURRY @ 14.5 PPG (YIELD = 1.41 / WGPS = 6.84) / DISPLACE WITH 22 BBL. WATER / 250PSI,PLUG DOWN ON 8/18/08,@ 330 AM 200 PSI SHUT IN,15 BBL. OF CEMENT RETURNS TO SURFACE . BACK OUT 9-5/8" LANDING JT./ MAKE UP 9-5/8" 11" NIPPLE AND WELL HEAD / NIPPLE UP BOP & RELATED EQUIPMENT. INSTALL TEST PLUG & TEST BOP PIPE & BLIND RAMS, CHOKE MANIFOLD VALVES, MUD CROSS VALVES, FLOOR VALVE KELLY @ 250# 5-MIN EACH & 1500# 10-MIN EACH. TEST 9 5/8" CSG @ 1500# 30-MIN. TEST PUMP & TEST_CHARTS_USED						
	TEST. ALL TESTED GOOD. ✓				ACCEPTED FOR RECORD AUG 2 5 2008	
14.	I hereby certify that the foregoing is true and c Signed Heather Riley		Regulatory Spec. D	ate <u>8/19/08</u>	FARRING ON FIELD OFFICE	
	(This space for Federal or State office use)					
	Approved by	Title			Date	
	Conditions of approval, if any:					