## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Amended

NOV 1 4 2008

	- व्यविति ,	,^ment
Sundry Notices and Reports on Wells	The Control of the Co	filce
	5.	Lease Number
		USA SF - 079391
1. Type of Well	6.	If Indian, All. or
GAS		Tribe Name
	7.	Unit Agreement Name
2. Name of Operator		
Burlington		
RESOURCES OIL & GAS COMPANY LP		San Juan 27-5 Unit
	<del></del> 8.	Well Name & Number
3. Address & Phone No. of Operator		
		San Juan 27-5 Unit 906
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No.
		30-039-30305
4. Location of Well, Footage, Sec., T, R, M		
	10.	Field and Pool
Surf: Unit G (SWNE), 1752' FNL & 1868' FEL, Section 8, T27N, R5W, NMPM		Blanco MV/Basin DK
BH: Unit G (SWNE), 2280' FNL & 1705' FEL, Section 8, T27N, R5W, NMPN		Complete and State
	11.	County and State Rio Arriba Co., NM
		Rio Al liba Co., INVI
Z Subsequent Report Plugging Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection  13. Describe Proposed or Completed Operations  07/17/08 MIRU AWS 711. NU BOP. PT csg to 600# 30/min – good test. RIH w/8 ¾" bit, tagged ahead to 3765'intermediate. Circ hole. RIH w/87 jts 7" 23# L-80 csg set @ 3757'. RU to cement FW, 10bbls Mud Clean, 10bbls FW. Pumped Scavenger 20 sx(60cf-11bbls) Class G Cement w/8 Flake, .4% FL-52, 5 #/sx LCM-1, .4% Sodium Metasilicate. Lead- pumped 490 sx(1044cf-186b .25\ #/sx Cello-flakes, .4% FL-52, 5 #/sx LCM-1, & .4% Sodium Metasilicate. Tail- pumped 90 .25#/sx Cello-Flake, .2% FL-52. Dropped plug and displaced w/146bbl water, circulated 66 bbls 07/22/08 PT csg to 1500# 30/min –good test. RIH w/ 6 ¼" bit. D/O cement. Drill ahead to 7895 RIH w/188 jts 4 ½" 11.6# L-80 LT & C casing set @ 7890'. RU to cement. 07/26/08 Pumped pr Scavenger -10 sx(30cf-5 bbls) Premium Lite HS FM cement w/.3% CD-32, 1% Fl-52, .25#/sx C (594cf-106bbls) Premium Lite HS FM Cement w/.25 #/sx Cello-Flake, 6.25 #/sx LCM-1, .3% C bbls FW & first 25bbls sugar water. Bumped plug. RD, RR @ 06:00 07/27/08.	c. 07/22/08. Pumpe 3% Bentonite, 3% (bls) Class G Ceme sx(124cf-22bbls) (cement to surface. TD. TD reached te-flush of 10 bbls (Cello-flake, 6.25 #/	d pre-flush of 10 bbls CaCl2, .25 #/sx Cello- nt w/8% Bentonite, 3% CaCl2, Class G Cement w/1% CaCl2, on 07/25/08. Circ hole. 07/26/08 chem. Wash & 2bbl FW. Pumpe //sx LCM-1. Tail- 300 sx
PT will be conducted by completion rig. PT & TOC will be recorded on next report.		
14. I hereby certify that the foregoing is true and correct.		
Signed Kelly Jeffery Title Regulator	y Technician	Date11/14/08 .
(This space for Federal or State Office use)  APPROVED BY		Date
CONDITION OF APPROVAL, if any:  Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of		ACCEPTED FOR RECORD
the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.		
		NOV 17 2008

**NMOCD** 

FARMINGTON FIELD OFFICE