

UNITED STATES
DEPARTMENT OF INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

DEC 15 2008

FORM APPROVED
Budget Bureau No 1004-0135
Expires March 31, 1993

SUNDRY NOTICE AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "Abandonment Field Office" for permit for such proposals

Bureau of Land Management
Farmington Field Office

Lease Designation and Serial No
Jicarilla Apache Contract #93

SUBMIT IN TRIPLICATE		6	If Indian, Allottee or Tribe Name Jicarilla Apache Nation
		7	If Unit or CA, Agreement Designation
1	Type of Well Oil Well Gas Well X Other	8.	Well Name and No Jicarilla 93 #15
2.	Name of Operator WILLIAMS PRODUCTION COMPANY	9.	API Well No 30-039-29810
3.	Address and Telephone No PO BOX 640 Aztec, NM 87410-0640	10.	Field and Pool, or Exploratory Area Blanco MV
4	Location of Well (Footage, Sec , T., R , M , or Survey Description) 1055' FSL & 280' FEL, Sec. 33, T27N, R3W	11	County or Parish, State Rio Arriba, NM

NSL-5963

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	Abandonment
<input type="checkbox"/> Subsequent Report	Recompletion
<input type="checkbox"/> Final Abandonment	Plugging Back
	Casing Repair
	Altering Casing
	<input checked="" type="checkbox"/> Other <u>SURFACE CASING</u>
	Change of Plans
	New Construction
	Non-Routine Fracturing
	Water Shut-Off
	Conversion to Injection
	Dispose Water
	(Note Report results of multiple completion on Well Completion or Recompletion Report and Log form)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12/13/08- TD 12 1/4" SURFACE HOLE @ 348', 1830 HRS

RAN 7 JTS, 9.5/8" SURFACE CSG, 36#, K-55, CSG SET @ 334', FLOAT INSERT @ 287'

CEMENT 9-5/8" CASING @ 334' - SHOE DEPTH / SINGLE SLURRY CEMENT JOB / 10 BBLs. FRESH WATER SPACER / 200 SXS TYPE 3 CEMENT + 2% CaCl-2 + .25#/SX CELLO FLAKE + 50.29 BBL. WATER = 83.79 BBL. (278 CuFt) SLURRY @ 14.5 PPG (YIELD = 1.41 / WGPS = 6.84) / DISPLACE WITH 22.5 BBL. WATER /1650 PSI PLUG DOWN ON 12/14/2008 @ 0000 27 BBL .OF CEMENT RETURNS TO SURFACE

12/14/08- INSTALL TEST PLUG & TEST BOP PIPE & BLIND RAMS, CHOKE MANIFOLD VALVES, MUD CROSS VALVES, FLOOR VALVE KELLY @ 250# 5-MIN EACH & 1500# 10-MIN EACH. TEST 9 5/8" CSG @ 1500# 30-MIN. TEST PUMP & TEST CHARTS USED ON ALL TEST. ALL TESTED GOOD.

RCVD DEC 18 '08
OIL CONS. DIV.
DIST. 3

ACCEPTED FOR RECORD

DEC 16 2008

14. I hereby certify that the foregoing is true and correct

Signed

Larry Higgins

Title Drilling COM

Date 12/15/08

FARMINGTON FIELD OFFICE

BY

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any

NMOCD

12/17