



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 1-14-09 Operator B7 America API #30-0 4532077
Property Name Atlantic BLS Well No. 23 Location: Unit F Section 4 Township 30 Range 10
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 90 Intermediate 838 Casing Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min					<u>90</u>
10 min					<u>90</u>
15 min					<u>90</u>
20 min					<u>90</u>
25 min					<u>89</u>
30 min					<u>86</u>

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>/</u>	<u>/</u>
Nothing		
Gas		<u>RCVD JAN 14 '09</u>
Gas & Water		<u>OIL CONS. DIV.</u>
Water		<u>DIST. 3</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: The intermediate is spud like casing - calling casing tubing. bradenhead has a puff when opened - int. blew hard for 2 min then down to deaden 4 min.

By Ray J. Pedraza
TECK
(Position)

Witness Mona Kuchling
tubing did not chug

E-mail address