

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

MAR # 2 2009

BUREAU OF LAND MANAGEMENT	WIAN EX 2003
Sundry Notices and Reports on Wells	Bureau of Land Management Farmington Field Office
i. Type of Well GAS	5. Lease Number SF-047020B 6. If Indian, All. or Tribe Name
. Name of Operator	7. Unit Agreement Name
BURLINGTON RESCURCES OIL & GAS COMPANY LP	
Address & Phone No. of Operator	8. Well Name & Number Congress 6E
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9. API Well No.
Location of Well, Footage, Sec., T, R, M	30-045-24838
Unit O (SWSE), 900' FSL & 1790' FEL, Section 35, T29N, R11W, NMPM	Otero Chacra
	11. County and State San Juan Co., NM
Casing Repair Water Shut off Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations	· .
	RCUD MAR 16'09 OIL CONS. DIV.
	DIST. 3
See attached for detail	,
4. I hereby certify that the foregoing is true and correct.	
igned Merry Menror Tracey N. Monroe Title Staff Regul	atory Technician Date 3/12/09
This space for Federal or State Office use)	ACCEPTED FOR PROC
PPROVED BY Title CONDITION OF APPROVAL, if any:	Date MAR 13 (003)
tile 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or traudulent statements or representations as to any matter within its jurisdiction.	PARMINOTON FIELD OFFI



3/3/09 MIRU AWS 746. ND WH. NU BOP. RU floor & tbg equip. Release & LD tbg hanger. TIH & tag PBTD @ 3000'. LD 1 ½" 2.9# J55 tbg. 3/4/09 PU 2 3/8" tbg. TIH w/4 ½" RBP set @ 2798'. Load hole w/2% KCL, attempt to PT csg, bled off from 550# to 440# in 5 min. RU swabbing lubricator. Swab off RBP. RD lubricator. Release RBP. TOH & LD RBP. TIH w/tbg. RU Nalco pump trk. Pumped 250 gal 15% HCL triple inhibited down tbg pump another 250 gal down csg. RD Nalco. TOOH w/tbg. 3/5/09 TOH w/tbg. PU 4 ½" RBP & TIH, set @ 2798'. Load hole w/2% KCL. Circ clean. Attempt to PT csg- no test. TOH w/ Tbg. 3/9/09 TIH w/4 ½" tension packer set @ 2772'. Attempt to PT csg from 2772' tp RBP @ 2798' – would not test. Tested Backside from 2772' – surface 500# 10/min – good test. Reset packer @ 2790'. Tested csg from 2790' – 2978' 500# 10/min – OK. Attempted to test backside – would not test. Hole located between 2772' – 2790'. Release packer. Pull back up to 2772' & set. PT backside to 500# 10/min. RU to swab for water production test. 4 swab runs, swabbed tbg down to 2340'. Recovered 9 bbls H2O. Recovered +/- 2.5 bbls production water – no gas. RD swab. 3/10/09 RU swab. Made 1st run @ 08:00, starting FL @ 1000' Ending FL @ 300'. REC 2.5 bbls H2O. 2nd run @ 09:00 starting FL @ 750' ending FL @ 300'. REC 1.75 bbls. 3rd run @ 10:00 FL @ 600' ending FL @ 300'. REC 1.5 bbls. RD Swab.

3/10/09 Notified Jim Lovato (BLM) & Steve Hayden (OCD) of hole

Between 2772' -2790'. TOC calculated to be @ 1860'. Request permission not to squeeze & BH did not show a leak. Verbal approval that no remediation required at this time by Jim Lovato (BLM) and Steve Hayden (OCD) w/request to Monitor BH.

3/10/09 Unseat packer TOOH. LD packer. RU retrieving head TIH latch onto & release RBP. 3/11/09 TOOH LD RBP. PU drift TIH w/94 jts 4.7# J-55 EUE 2 3/8" tbg. Set @ 2910', FN @ 2908'. RD floor. ND BOP NU tree. RU to swab. Starting FL @ 1900', ending FL @ 2300'. 12 runs recovered 23 bbls water no gas. RD swab. RD AWS 746 & equip, turned over to production. RD RR @ 17:00 hrs 3/11/09