



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distnc.htm](http://emnr.state.nm.us/ocd/District%20III/3distnc.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-7-09 Operator Devon Energy API # 30-0 45-30 283
Property Name NEBY Well No. 58M Location: Unit Section 13 Township 31 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 126 Intermediate 232 Casing 234 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min		<u>4</u>		<u>38</u> 115	<u>115</u>
10 min				<u>30</u>	<u>101</u>
15 min				<u>23</u>	<u>87</u>
20 min				<u>21</u>	<u>82</u>
25 min				<u>19</u>	<u>80</u>
30 min				<u>19</u>	<u>82</u>

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		<u>✓</u>
Surges		
Down to Nothing		
Nothing	<u>✓</u>	
Gas		<u>✓</u>
Gas & Water		
Water		

RCVD APR 7 '09

If bradenhead flowed water, check all of the descriptions that apply below:

OIL CONS. DIV.
DIST. 3

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 178

REMARKS:

Nothing on braden head when opened.
Started (needed to blow down on other side) Pres. at restart 218 Int. Casing 221
Blew hard whole time

By Phil Jank
LEASE OPERATOR Tech
(Position)

Witness Monica Kuehling

E-mail address