NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-7-09 Operator Devon Energy API #30-0 45-31090

Property Name NEBU Well No. 319M Location: Unit ___ Section 7 Township 31 Range 6

Well Status(Shut-In or Producing) Initial PSI: Tubing 173 Intermediate 575 Casing 171 Bradenhead 051

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min		577	167 ~~577~~		175
10 min		577	170 ~~577~~		177
15 min		575	171 ~~0~~		177
20 min					178
25 min					179
30 min					175

FLOW CHARACTERISTICS	BRADENHEAD	INTERMEDIATE
Steady Flow		✓
Surges		
Down to Nothing	✓	
Nothing		
Gas/Air Bad smell		
Gas & Water		✓
Water		

RCVD APR 7 '09
OIL CONS. DIV.
DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ____ FRESH ____ SALTY ____ SULFUR ____ BLACK ____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: Bradenhead Blew to fumes in 30 seconds to nothing in 1.5 minutes Intermediate - hard blow first 30 then to flow in 1.04 minutes flowed for 5 minutes then fumes for rest of 30

By [signature] Witness Monica Cushing

LEASE OPERATOR TECH
(Position)

E-mail address ____