



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-1-09 Operator Lively Expl API #30-0 45 21017
Property Name Lively Well No. 2 Location: Unit 21 Township 28 Range 8
Well Status(Shut-In or Producing) Initial PSI: Tubing 200 Intermediate 0 Casing 240 Bradenhead 15

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			
	Bradenhead	INTERM		
	Int	Csg	Int	Csg
5 min	0			250
10 min	0	245		250
15 min	0	245		
20 min				
25 min				
30 min				

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	RCVD MAY 1 '09
Gas & Water	OIL CONS. DIV.
Water	DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☒ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 1

INTERMEDIATE 0

REMARKS:

Bradenhead flowed clear water 15oz in 15 seconds then nothing - dripping - Intermediate bleed down in 15 seconds misty air

By [Signature]
(Position)

Witness Monica Kuehling

Possible no water before.

E-mail address _____