



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnrd.state.nm.us/ocd/District III/3distr.htm](http://emnrd.state.nm.us/ocd/District%20III/3distr.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-16-09 Operator Burlington API #30-0 45-21155

Property Name Riddle G Well No. 2 Location: Unit Section 7 Township 28 Range 8

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing N/A Intermediate N/A Casing 10 Bradenhead 42

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min			10		
10 min			10		
15 min			10		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>1/4"</u>	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water <u>✓</u>	
Water <u>✓</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ✓ FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 27

INTERMEDIATE N/A

REMARKS:

this is a run hole - Blew down immediately
then flowed small steam 1/4"

By Russell Elliott
Senior M50
(Position)

Witness Monica Cochran

E-mail address

