



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-16-09 Operator Burlington Res API #30-0 45-21156

Property Name Riddle G Well No. 3 Location: Unit I Section 17 Township 28 Range 8

Well Status (Shut-In or Producing) Initial PSI: Tubing 11/1 Intermediate 11/1 Casing 11/1 Bradenhead 11/1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min			111		
10 min			111		
15 min			111		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow 11/1

Surges


Down to Nothing

Nothing

Gas

Gas & Water

Water



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 9

INTERMEDIATE 11/1

REMARKS:

Slm hole - flowed into tank

By

Russell Elliott

Witness

Monica Fekken

Senior MSD

(Position)

E-mail address