



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170

[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-16-09 Operator Burlington Gas API #30-0 45 23699
Property Name Scrambling A Well No. 1A Location: Unit 21 Section 21 Township 28 Range 8
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 12 Intermediate N/A Casing 50 Bradenhead 7

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min			49		
10 min			49		
15 min			49		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	/
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 1

INTERMEDIATE N/A

REMARKS:

Blew down in 5 seconds

By Russell Elliott
Senior MSD
(Position)

Witness Monica Kuehling

E-mail address _____

