



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emmr.state.nm.us/ocd/District III/3district.htm](http://emmr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-1-09 Operator Lively Explor. API #30-0 45-23969
Property Name Lively Well No. 2E Location: Unit Section 21 Township 28 Range 8
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 129 Intermediate 53 Casing 129 Bradenhead 30

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing TIME	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	525	141	light blow	145
10 min	0	525		James	145
15 min	0	525	142	James	145
20 min				James	145
25 min				James	145
30 min				James	145

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow	✓
Surges	RCVD MAY 1 '09
Down to Nothing	OIL CONS. DIV.
Nothing	DIST. 3
Gas	✓ James
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

Braden head blew down in 6 seconds
Intermediate head blew to whistle in 3 minutes
light blow to James in 6 minutes

By [Signature]
[Signature]
(Position)

Witness Monica Luckling

E-mail address