



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III3district.htm](http://emnr.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4 May 2009 Operator Lively Exp. API #30-0 95-21257
Property Name Lively Well No. 13 Location: Unit 1A Section 18 Township 28N Range 8W
Well Status (Shut-In or Producing) Initial PSI: Tubing 138 Intermediate 118 Casing 151 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	118	151	TLTm	160
10 min	0	118	154	TLTm	160
15 min	0	118	159	TLTm	142
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		X
Nothing	X	
Gas		X
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE TLTm

REMARKS:

Int Blew Down To Nothing in 44 seconds

By [Signature]

Witness _____

(Position)

E-mail address _____

